


ELENZIO 2T4S



Montageanleitung / Notice de Montage / Assembling Instruction

ART. NR: 13 087 300

EAN: 40 10 340 18 73 05

ORDER : 18422

DE: Wichtige Montage – Tipps hier zum herunterladen:

EN: Important assembling suggestions download:

FR: Conseils de montage importants à télécharger ici :

BG: Важни съвети за сглобяване, които да изтеглите от тук:

CZ: Důležité montážní tipy ke stažení zde:

EE: Olulised kokkupanemisetepanekute allalaadimine:

DK: Vigtige montage tips til at downloade:

ES: Descarga de sugerencias de montaje importantes:

FI: Tärkeät kokoamisedotukset ladataan:

GR: Λήψη σημαντικών προτάσεων συναρμολόγησης:

HR: Preuzimanje važnih prijedloga za sastavljanje:

HU: Fontos összeszerelési javaslatok letöltése:

IT: Download importanti suggerimenti di montaggio:

LT: Svarbūs surinkimo pasiūlymai atsisiųsti:

LU: Wichtig Versammlungsvorschläge eroflueden:

LV: Svarīgu montāžas ieteikumu lejupielāde:

NL: Belangrijke montagesuggesties downloaden:

NO: Viktige nedlastingsforslag:

PL: Pobieranie ważnych sugestii montażowych:

PT: Download de sugestões importantes de montagem:

RO: Descărcare de sugestii importante de asamblare:

RS: Преузимање важних предлога за састављање:

RU: Важные предложения по сборке скачать,:

SL: Prenos pomembnih predlogov za sestavljanje:

SE: Viktiga hämtningsförslag:

SK: Stiahnutie dôležitých návrhov na zostavenie:

TR: Önemli montaj önerileri indir:

ARB: المهمة التجميع اقتراحات تنزيل:

 **Inter Link**®

Z. A. du Niederwald

F-67470 Seltz

www.interlink-sas.com




Colli 1/2		
C	894x378	1x
D	894x378	1x
F	1154x80	1x
H	374x350	2x
R	350x111	8x
S	317x109	4x
Y	798x362	1x
Y1	798x362	1x

Colli 2/2		
A	1154x363	1x
B	1192x400	1x
G	820x390	1x
G1	820x390	1x
G2	820x390	1x
I	817x387	1x
J	817x387	1x
M	356x347	4x
T	387x202	4x









Colli 1/2		
1	1383x80x2,5	2x
2	394x80x2,5	2x
Colli 2/2		
3	1296x74x2,5	2x
4	400x74x2,5	2x

ELENZIO 2T4S




Z1		36x
Z2		1x
Z3		12x
Z16		32x
Z29		16x
Z29		8x
Z30		29x
Z33		29x
Z58		12x
Z67		4x
Z68		16x
Z78		8x
Z90		6x
Z114		8x
Z156		18x
Z166		12x
Z167		12x
Z178		36x
Z189		4x
Z269		6x

Z16		4x
Z75		2x
Z81		2x
Z140		2x



2.




Y	798x362	1x
---	---------	----

Z1		4x	Z78		2x
Z30		2x	Z114		4x

Z67		4x	350mm
Z68		8x	EURO 6x13

3.




Y1	798x362	1x
----	---------	----

Z1		4x	Z78		2x
Z30		2x	Z114		4x

Z67		4x	350mm
Z68		8x	EURO 6x13


4.



C	894x378	1x
---	---------	----

Z1		2x	Z78		2x
Z30		2x	Z90		2x
			Z33		2x


5.



D	894x378	1x
---	---------	----

Z1		2x	Z78		2x
Z30		2x	Z90		2x
			Z33		2x

6.




A	1154x363	1x
---	----------	----

Z1		4x
----	--	----


Z30		4x
Z33		1x

7.







Z3		2x
----	--	----


8.



Z3		2x
----	--	----




13.




B	1192x400	1x
---	----------	----

Z33		8x
-----	--	----

14.




15.



G	820x390	1x
G1	820x390	1x
G2	820x390	1x



16.



17.



X=Y



Z178		12x
------	--	-----

Three icons at the top right show the correct (smiley face, checkmark) and incorrect (frowny face, X) placement of the screws.

18.



X=Y



Z167		12x
Z178		12x

Three icons at the top right show the correct (smiley face, checkmark) and incorrect (frowny face, X) placement of the screws.

19.





X=Y

Z156		18x
------	--	-----

Three icons at the top right show the correct (smiley face, checkmark) and incorrect (frowny face, X) placement of the screws.

20.

A large black arrow points from the left side of the cabinet towards the right side.

21.

Z140

! X ✓

Ø8

Z140		2x
------	--	----

22.

Z75 Z140 Z81

PZ 2

Z75		2x
Z81		2x

23.

Z16 Z16 Z140

PZ 2

Z16		4x
-----	--	----


24.

S

Z1

S	317x109	4x
Z1		8x


25.



R	350x111	8x
---	---------	----

Z1		8x
Z30		16x


26.



T	387x202	4x
---	---------	----

Z33		16x
-----	--	-----


27.



Z3		8x
----	--	----

Z58		8x
Z166		8x
Z269		4x


28.



M	356x347	4x
---	---------	----

Z16		24x
Z67		4x
Z178		12x


29.



I	817x387	1x
J	817x387	1x


Z166		4x	Z16		8x
			Z189		4x

30.




Z58		4x
Z269		2x

31.



Z29		16x
Z29		8x

32.



H	374x350	2x
---	---------	----